Photograph was taken at the time of Inspection (05.04.2018) Improvements to drain at Vijayalakshmi layout at Bagalagunte in Ward No.14, BBMP, Bangalore.



ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Scanned by CamScanner

Photograph was taken at the time of Inspection (05.04.2018) Improvements to drain at Vijayalakshmi layout at Bagalagunte in Ward No.14, BBMP, Bangalore.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Bangalore

Scanned by CamScanner

CIVIL-TECH CONSULTANTS AND ENGINEERS

Building & Highway Material Testing Laboratory
An ISO 9001:2008 Certified Company
NABL - Accredited Laboratory as per ISO / IEC-17025 : 2005

Job No.: CTCE/BBMP/JCR/Consultants/04/2018-19

Dated: 06.04.2018

To,
Executive Engineer,
Dasarahalli Division,
BBMP, Bangalore.

Sir,

Sub: **Consultancy Services for the work of Improvements to drain at Vijayalakshmi layout at Bagalagunte in Ward No.14, BBMP, Bangalore.**

Ref: 1) EE/DD/WO/207/2017-18/ Date: 23.01.2018
2) Job Code: 014-18-000017

We are herewith forwarding to **Mr. J.C Ramachandra,** 1st and Final Bill duly verified and certified that the work is satisfactory and for a Gross Value of Rs. 50,10,428/- (Rupees Fifty Lakhs Ten Thousand and Four Hundred and Twenty Eight only) for further needful.

Thanking you,

Yours faithfully,
For Civil-Tech Consultants and Engineers

6.4.2018
Chief Executive Officer

#23/14, 7th Cross, 3rd Stage, 4th Block, Shakthi Ganapathi Nagara, Basaveshwaranagar, Bangalore-79.
Tele Fax : 23223227, Website : www.civiltechconsultants.com
E-mail : vishwanath.ia@civiltechconsultants.com / info@civiltechconsultants.com

Scanned by CamScanner